



Insert a plug into the bottom end of the support leg tube.



Slot the aluminium arm onto the support leg tube.





Fis the aluminium arm to the leg of the hoop with the KH 25 fitting



Lay the slatted staging top onto the aluminium arms. Fix to the aluminium arms from the underside at each corner.